

Handwritten notes in the top right corner, possibly including the word "Carga" and other illegible text.

## ANEXO I

Ejemplos de impresos de inspecciones de contenedores *ON HIRE*

# ON HIRE SURVEY REPORT

<b>EUROMAR srl</b> GENGA - ITALY	EQUIPMENT N.			CUSTOMER:			DEPOT: <u>Bologna</u>					
	PREFIX <u>CLW</u>	SERIAL <u>235192</u>	CD <u>0</u>	<u>SOMPART</u>						CITY: <u>Bologna</u>		
CTR <input checked="" type="checkbox"/> 20 <input type="checkbox"/> 40 <input checked="" type="checkbox"/> ST <input type="checkbox"/> 2 AL <input type="checkbox"/> 3 PL <input checked="" type="checkbox"/> BX <input type="checkbox"/> 2 OT <input type="checkbox"/> 3				SURVEY N.	STATUS	DAY <u>12</u>	MONTH <u>04</u>	YEAR <u>94</u>				

LEFT SIDE: Paint edge damage

B/RAIL: \_\_\_\_\_

T/RAIL: \_\_\_\_\_

RIGHT SIDE: Paint panels edge damage

B/RAIL: \_\_\_\_\_

T/RAIL: \_\_\_\_\_

ROOF/TARPAULIN: \_\_\_\_\_

INTERIOR: \_\_\_\_\_

UNDERSIDE: \_\_\_\_\_

BCM: \_\_\_\_\_

FLP: \_\_\_\_\_

FRONT: \_\_\_\_\_

SILL: \_\_\_\_\_

HEADER: \_\_\_\_\_

CORNER POST: \_\_\_\_\_


RIGHT DOOR: \_\_\_\_\_

LEFT DOOR: \_\_\_\_\_

SILL: \_\_\_\_\_

HEADER: \_\_\_\_\_

CORNER POST: \_\_\_\_\_



SPECIAL REMARKS: TARE 2380

BLD DATE: ACEP

CSC EXP: 02-98

MAX GROSS: 24000

ACCEPTED AS PER IICL \_\_\_\_\_ EDITION

ACCEPTED AS PER STANDARD

ABBREVIATE AS FOLLOWS: B = BENT - C = CUT - D = DENT - I = INSERT - L = LOOSE - R = TOTAL REPLACEMENT - S = PREVIOUS STRAIGHTENED - W = WELD - V = VULCANIZED - X = EXISTING REPAIR - Z = SCRATCHED - IR = IMPROPER REPAIR ONLY FOR TARPAULIN: P = PATCH WITHOUT CUSTOM SEAL - PS = PATCH WITH CUSTOM SEAL

DEPOT REPRESENTATIVE: \_\_\_\_\_